




Porch Rail




1 5/8 x 3 1/2




1 5/8 x 2 1/2




1 5/8 x 3 5/8



1 5/8 x 3 5/8









1 5/8 x 2 5/8, 3 5/8




1 5/8 x 2 5/8, 3 5/8

Porch Rail




Porch Rail




10413
3 5/8 x 4 5/8


Handrail




1 5/8




1 3/4 x 2 3/4




1 3/4 x 3 3/8



1 3/4 x 4 1/2








1 3/8 x 5




Fraser
Millworks

Handrail




Handrail




10515

3 1/2 x 2 1/2



10519


1 3/8 x 3 3/8



10519-1


1 3/8 x 1 3/8

Baluster detail




10518

2 1/2 x 6 1/2




Fraser
Millworks

Handrail




10520

$1 \frac{15}{16} \times 1 \frac{9}{16}$




10521

$1 \frac{7}{8} \times 3 \frac{1}{2}$




10523

$1 \frac{1}{4} \times 5 \frac{1}{2}$




10522

$1 \frac{1}{2} \times 3 \frac{1}{2}$




10524

$2 \frac{1}{16} \times 3 \frac{5}{8}$




Fraser
Millworks

Handrail




10525

1 1/2 x 2 1/4




10526

1 1/2 x 3 1/2




10528

2 5/8 x 2



10527

2 1/4 x 3 3/4




10529

1 1/2 x 4 1/2




Fraser
Millworks


Handrail




10530
1 7/8 x 4




10531
3/4 x 1 1/2



10532
1/2 x 1 3/32
fillet



10533
1 3/4 x 2 3/8




10534
2 1/2 x 3 3/8




Fraser
Millworks


Handrail



10535
3 1/16 x 3 1/16




10537
2 1/16 x 4 1/4




10536
2 x 4




Handrail




10538
 $2 \frac{3}{4} \times 3 \frac{5}{8}$



10539
 $1 \frac{1}{2} \times 2 \frac{1}{2}$



10540
 $2 \frac{3}{16} \times 2 \frac{1}{2}$




10541
 $1 \frac{5}{16} \times 2 \frac{1}{8}$




Fraser
Millworks


Handrail




10542
 $1\frac{1}{2} \times 4$



10543
 $2\frac{1}{4} \times 2\frac{5}{8}$



10544
 $1\frac{1}{2} \times 5\frac{7}{16}$




10545
 $1\frac{1}{2} \times 5\frac{1}{4}$




Fraser
Millworks


Handrail



10546
2 5/8 x 3 5/8




10548
1 3/4 X 3




10547
2 5/8 X 4 5/8


Handrail



10549
 $1\frac{1}{2} \times 5\frac{5}{8}$




10550
 $3\frac{1}{2} \times 4\frac{1}{2}$




10551
 $2\frac{1}{2} \times 3\frac{1}{2}$




Handrail




10552
 $3 \frac{9}{16} \times 2 \frac{5}{8}$



10553
 $1 \frac{1}{2} \times 5 \frac{1}{2}$



10554
 $1 \frac{3}{4} \times 1 \frac{7}{8}$




10555
 $1 \frac{3}{16} \times 2 \frac{5}{8}$




Fraser
Millworks


Handrail




10556
1 1/2 x 5 1/2



10557
1 9/16 x 5 1/4



10558
1 1/2 x 4



Fraser
Millworks