

















Rounds




Fraser
Millworks


Rounds




9820
2 x 2




9821
 $3/4 \times 3 \frac{9}{16}$




9823
 $3/4 \times 1 \frac{1}{2}$




9824
 $5/8 \times 5/8$




9822
 $1 \frac{5}{8} \times 4 \frac{3}{8}$



9826
 $3 \frac{1}{8} \times 3 \frac{1}{8}$




9825
2 1/2




Fraser
Millworks

Rounds




9827

3 1/4




9828

1 5/8




9829

1 1/2




9830

2 3/8 x 2 3/8




9831

1 1/2 x 1 1/2




9832

1 1/2 x 1 1/2



9833

1 1/4 x 1 1/4



9821-1

1/2 x 3/4



Fraser
Millworks